

FIG. 1




FIG. 2






FIG. 3






FIG. 4







FIG. 5

SEVENTH STEP



EIGHTH AND
NINTH STEP



COMPLETE




FIG. 6




FIG. 7




FIG. 8






FIG. 9




FIG. 10






FIG. 11




FIG. 12






FIG. 13





FIG. 14






FIG. 15






FIG. 16






FIG. 17




FIG. 18






FIG. 19





FIG. 20






FIG. 21




FIG. 22






FIG. 23




FIG. 24




FIG. 25






FIG. 26a




FIG. 26b






FIG. 27




FIG. 28






FIG. 29




FIG. 30






FIG. 31
(PRIOR ART)





FIG. 32
(PRIOR ART)






FIG. 33a




FIG. 33b






FIG. 34a





FIG. 34b






FIG. 35






FIG. 36




FIG. 37






FIG. 38




FIG. 39a




FIG. 39b




FIG. 39c






FIG. 40





FIG. 41



PHYSICAL VALUES AND SPUTTER RESISTANCE OF STRESS RELAXATION LAYER CANDIDATE MATERIAL
(X: OCCURRENCE OF CRACKS, Δ: OCCURRENCE OF WRINKLE, O: NO ABNORMALITY)